

SF6 PPE Kit

Anytime SF6 is exposed to arcing events, proper PPE should be worn to protect against acidic and potentially toxic decomposition byproducts. The GasQuip PPE Kit offers skin and breathing protection for operators, a means of neutralizing acidic byproducts, and materials to cleanup and dispose of hazardous materials when performing maintenance on gas insulated equipment.





Includes:

Blue Tote

DuPoint Tyvek Coverall Suit

Breathing Half-Face Mask (N95)

Full Face Respirator with Acid Vapor Cartridges

Chemical Resistant Latex Gloves

Work Gloves

Sodium Carbonate

GasQuip SF6 Field Handbook

Cleaning Cloths

Alcohol Spray Bottle

Ph Test Strips

Spoons

Safety Helmet

Duct Tape

Hazmat Bags